




5/23/2013

Identifying and Fixing Hardware & Software Faults

Unit 13: P4, P5, P6, M2, M3; Partially covers P2

Unit 25: P5, P6, M2, M3, D1, D2; Partially covers P4



Richard Hancock

1 CONTENTS

2	Introduction	2
3	Finding the Fault and Suggesting Upgrades.....	2
3.1	Client's Observations	2
3.2	Analyzing/Testing the Computer	2
3.3	Recommended Upgrade	5
4	Applying the Fault Remedy	8
4.1	Preparations.....	8
4.2	Fixing the Hardware Faults	12
4.2.1	Cleaning the PC	12
4.2.2	Installing the CPU Cooler	22
4.2.3	Quick Test after Fan Install.....	32
4.3	Fixing the Software Fault	33
4.4	Fully Retesting the System.....	38
5	References	40

2 INTRODUCTION

In this report I will be documenting the repair process of a faulty computer that was given to me by a client to fix. I will be providing photographic evidence of the diagnostic and repair process. Then I will evaluate if the repair has fixed the initial fault and whether future upgrades may be required at a later date.

3 FINDING THE FAULT AND SUGGESTING UPGRADES

3.1 CLIENT'S OBSERVATIONS

The client had sent the computer for repairs due to increased slowdown of programs that ran fine weeks earlier. He also observed that there was a strange noise coming from inside of the computer. They also commented that they had the computer repaired for the same fault, less than a two months ago. However the client has no idea what repairs were carried out to the computer.

From this information I believe the problem is related to overheating because the strange noise will most likely be a faulty fan. This is probably causing the CPU to overheat and lower its performance to compensate for the increased heat.

It could also be the hard drive, as it is the only other possible cause of a strange noise (because it has moving parts). However if the hard drive failed the computer would not be able to load the operating system, so this isn't a likely cause.

3.2 ANALYZING/TESTING THE COMPUTER

To begin with I downloaded the temperature monitoring software CPUID HWMonitor. This software will allow me to access the temperature sensor's readouts.

AMD Phenom II X6 1090T			
Temperatures			
Core #0	50 °C (122 °F)	50 °C (122 °F)	59 °C (138 °F)
Core #1	55 °C (131 °F)	53 °C (127 °F)	62 °C (143 °F)
Core #2	50 °C (122 °F)	49 °C (120 °F)	58 °C (136 °F)
Core #3	54 °C (129 °F)	54 °C (129 °F)	61 °C (141 °F)
Core #4	55 °C (131 °F)	55 °C (131 °F)	59 °C (138 °F)
Core #5	55 °C (131 °F)	53 °C (127 °F)	62 °C (143 °F)

These temperatures seem abnormally high for an AMD processor as they are designed to run at lower temperatures. After a search for the model number on google "AMD Phenom II X6 1090T" I found that the maximum operating temperature was between "55°C - 62°C". [\[1\]](#)

Maximum operating temperature 55°C - 62°C

That means that the processor is hovering a few degrees below its max operating temperature while idle, which means that when running programs or games that will significantly increase the load on the processor, the temperature will be way above its max.

Next I ran some high end games for a few minutes to see what the temperature would reach. Just Cause 2 has a built in benchmarking mode that will create some complex graphical scenes that will stress the GPU and CPU to run. However while running this test I had to be careful of the temperature being too high for an extended period of time, because this could significantly shorten the lifespan of the processor.



Just Cause 2's Benchmark Mode



Just Cause 2 Benchmark Results

System Fan 3	100 %	100 %	100 %
AMD Phenom II X6 1090T			
Temperatures			
Core #0	86 °C (186 °F)	84 °C (183 °F)	86 °C (186 °F)
Core #1	87 °C (188 °F)	85 °C (185 °F)	88 °C (190 °F)
Core #2	83 °C (181 °F)	79 °C (174 °F)	84 °C (183 °F)
Core #3	84 °C (183 °F)	81 °C (177 °F)	86 °C (186 °F)
Core #4	87 °C (188 °F)	85 °C (185 °F)	88 °C (190 °F)
Core #5	87 °C (188 °F)	81 °C (177 °F)	88 °C (190 °F)
Powers			


I had to stop the test slightly early because the above temps were way too high. The temperature monitoring program also showed that the fan was only spinning at 2000RPM which is pretty slow for an AMD stock cooler. After looking on the internet I found that the max speed of this fan was 6000-7000 RPM. This means that the fan on the stock cooler is faulty and needs to be replaced.

The stock cooler could be fixable by dismantling the fan (maybe replacing the bearings or motor), but it would probably easier and more efficient to just replace it with an aftermarket cooler.

Just to be sure on these results I ran another benchmarking tool, to make sure that the processor is not faulty, as the user reported it running significantly slower than normal. This could mean that the overheating has already damaged the processor and it will need to be replaced, which is a way more costly replacement.

I ran the tool Performance Test by PassMark, which rates a computer's hardware based on a number of stress tests. The program will then let you compare these results with other hardware or the exact same

model.



These results show that the processor is running at 63.1% of its potential.

3.3 RECOMMENDED UPGRADE

After looking at the results of the analysis I recommend that a new cooler is needed to replace the faulty cooler.

I specifically recommend the “Zalman CNPS9500A LED Heat sink and Fan” [\[2\]](#)[\[3\]](#) for these reasons:

- Good ratings and reviews on most websites, usually means it's a reliable product.
- Compatibility with the AM3 socket type of the processor
- High performance which will make it perfect for gaming, rendering or other intensive tasks.
- Future proof can be used on most Intel and AMD CPU sockets.
- Should allow the user to overclock their CPU without worrying about the heat.
- It also comes with a fan controller that allows you to adjust the fan speed for when you need full fan RPM, or you just want it to be quieter.

However there are a few drawbacks:

- Might be too large for most cases, so there might be a problem if the RAM or North Bridge is too close the CPU.
- No automatic fan speed control because it is 3-pin (4th pin allows for PWM control (Motherboard Automatic Control)), so the user must be proactive in adjusting the fan controller when the CPU needs it.
- Really sharp fins and can cause injury when installing.



Another item that is needed is some high quality Thermal Paste to efficiently transfer the heat from the CPU to the cooler Also some thermal paste remover to get rid of the previous thermal paste and purify the surface.

I have found a combo pack of these items with high quality “Arctic Silver 5” thermal paste. [\[4\]](#)



Also pictured above is the anti-static service kit needed to carry out this repair safely without any static damage to the components. [5]

I will also use some Compressed air [6][7] to clean out a lot of the dust buildup in the computer, which should help the system run generally cooler and help the fans to circulate the air more efficiently.



4 APPLYING THE FAULT REMEDY

4.1 PREPARATIONS


Before performing any upgrades to the computer, I made a backup on an external hard drive of all the data on the hard drive, especially irreplaceable data i.e. personal pictures, videos, documents and saves. I copied all of the files from the user folder to the external hard drive which covers most of the irreplaceable data and left most of the program files, as these can be easily reinstalled/downloaded. While performing this upgrade there is a very low chance of file loss as the hard drive will not be moved or interacted with in any way.




External Hard Drive Enclosure

	Name	Type	Size
	AppData	File folder	
	Contacts	File folder	
	Desktop	File folder	
	Downloads	File folder	
	jagexcache	File folder	
	Links	File folder	
	My Documents	File folder	
	My Music	File folder	
	My Pictures	File folder	
	My Videos	File folder	
	Saved Games	File folder	
	Searches	File folder	
	.gitconfig	GITCONFIG File	1 KB
	jagex_cl_oldschool_LIVE.dat	DAT File	1 KB
	jagex_cl_runescape_LIVE.dat	DAT File	1 KB
	random.dat	DAT File	1 KB


User's Data on original system




Compressing the files into a zip file, which will reduce the file size



Compressing all the files takes a few minutes




I then copy the zip file across to the external hard drive



The zip file is now on the external hard drive, it is then disconnected and stored in a safe location

I also had to set up the anti-static precautions to protect the computer equipment from ESD (Electrostatic Discharge). This involved laying out the ESD mat and connecting the black grounding wire to a suitable location. Ideally the ground would be connected to the ground on a plug socket, but I didn't have the ability to do this so I connected the ground to an object with a lower electrical resistance. The ESD mat also had a wrist strap that grounded me as well and the computer equipment.





ESD Wrist Strap connected to ESD Mat and ground

4.2 FIXING THE HARDWARE FAULTS

Once the precautions had been setup I could begin with the repair process. I am also while doing this process, cleaning the exterior and interior of the computer.

4.2.1 Cleaning the PC

I used a micro-fiber cloth and a damp cloth to clean most of the exterior of machine and accessories. While I used a can of compressed air to clean the vents, fans and interior.

I partially filmed the cleaning process, the video should be available at: <http://youtu.be/vRVTP8s3XRg> or included with this file in lower quality. *The camera I used to film it is pretty broken and audio loses sync throughout.*



Keyboard Before



Keyboard After

Unfortunately the keyboard had been stored in a cupboard for a while, so most of the dust was deeply ingrained.


I then moved on to the exterior of the case.



Before Picture



Before Picture



Before Picture



Before Picture




After Picture



Cleaning in progress




Cleaning in Progress



Cleaning in Progress

Richard Hancock - Unit 25 & 13




After Picture



Before Picture




Cleaning in progress




After Cleaning




Before Picture



After Picture




Before Picture



After Picture



Before Picture




After Picture



After Picture (No before picture for this part unfortunately)

4.2.2 Installing the CPU Cooler


Once the cleaning was finished to an acceptable standard, I started the repair process. First I removed the faulty CPU cooler by releasing the lock latch and pushing the cooler down slightly to relieve pressure on the clips that hold it in place.




Picture of Faulty CPU cooler, with the latch highlighted in red.

AMDs CPU coolers are a lot easier to replace than Intel as they are usually held on with clips for a screwless install/uninstall. While pulling it out I made sure not to damage any other nearby components

(Processor, RAM or the North Bridge). I also made sure to disconnect the fan 4-pin connector carefully to avoid bending the pins.




Picture of the faulty CPU cooler removed



Picture of the faulty CPU cooler removed, also seen is thermal paste residue.



Close up of the latch and clip that I was talking about earlier.



Close up of other clip

The CPU was still covered in a lot of thermal paste residue that needed to be cleaned with the special cleaning fluid brought earlier. This should make the CPU look good as new and be ready for a new coat of thermal paste.



CPU before any cleaning



Using the Thermal Paste remover and a lint free cloth, I started wiping away the Thermal paste



CPU after 1st cleaning fluid applied.



I then applied the second fluid using the other side of the same lint free cloth



The CPU is now ready for thermal paste

Once the CPU was ready for thermal paste I started preparing the CPU cooler for placement. After being confused by the strange clipping mechanism and reading the not very helpful manual, I got it ready for attachment.




The CPU cooler attaches by getting one of the clips attached and then forcing the other one down to clip in as well.

Then I start applying the Thermal Paste to the CPU using the card method. I chose the card method (spreading the thermal paste with a card) because it is a lot more reliable at covering the entire CPU with no gaps. The downside to this method is the air bubbles that develop while spreading the paste, these bubbles can ruin the conductivity of the paste in some areas which will heighten the temperature


by a few degrees.

Other people prefer the pea method, which is to drop a pea sized amount of thermal paste in the middle of the CPU cooler and let the CPU cooler spread it when it is pressed down and installed. The downside to this method is that if the wrong amount of paste is used it might not cover all the CPU, and there would be no way to check if it has until you notice high temperatures.




CPU after Thermal Paste is applied

I couldn't take pictures while installing the CPU Cooler because I needed both hands to make sure I didn't drop the fan on any of the nearby components. Below is a diagram for the manual [8] that illustrates how to attach the fan.




Source: Zalman CNPS9700 / 9500A LED User Manual [8]


It was easy to get the first clip attached, but the second took a lot of strength to push into place. I was originally worried that the clips wouldn't secure the CPU cooler enough, but after attaching it I feel that it's very secure.



CPU cooler is attached and secure.




Close up on one of the push down clips. (Couldn't photograph the other one because it's masked by the cooler)



Wide shot of installation and me holding the fan connector while still wearing my ESD wriststrap.

Next I needed to connect the fan controller's 3-pin connector to the motherboards CPU fan port, unfortunately the CPU covers most of the port so trying to get it connected was tough. I also needed to run this cable to the outside of the case so that the user could access the fan controller.




Fan controller cable running out of the case and back in.

I attached the Fan controller to the side which does leave the wires running along the outside of the case quite a distance. Some tape could cover this wire, or drilling a hole closer to the fan controller. However there no danger in leaving them like this unless they get damaged.



Fan controller with cables attached.




Picture from much later in the repair process with the fan controller on the side, and the less than ideal cable run.

The user could also later invest in a more expensive fan controller that will fit in a CD drive bay, so there would be no exposed wires.


4.2.3 Quick Test after Fan Install

After the fan was installed but before putting the case back together, I decided to test the fan to make sure it is working. So I connected a Monitor, Mouse, Keyboard and then the power.



Essentials connected and ready to turn on the computer.

I quickly turned on the PC to check if the fan would start turning, because if it didn't I would need to turn it off again quickly to avoid extreme overheating. Fortunately this wasn't necessary because the fan lit up and started rotating.



Fan lit up in blue and rotating


After waiting a few minutes for the computer to boot up, I opened the CPUID HWMonitor to check the temperature, and there was a very noticeable difference of around 30-40°C

FANINFO		2384 RPM	2384 RPM	2415 RPM
ns PWM				
CPU	100 %	100 %	100 %	
System Fan 1	100 %	100 %	100 %	
System Fan 2	100 %	100 %	100 %	
System Fan 3	100 %	100 %	100 %	
Phenom II X6 1090T				
Temperatures				
Core #0	20 °C (68 °F)	17 °C (61 °F)	20 °C (68 °F)	
Core #1	20 °C (67 °F)	16 °C (61 °F)	20 °C (67 °F)	
Core #2	20 °C (68 °F)	16 °C (61 °F)	20 °C (68 °F)	
Core #3	20 °C (68 °F)	16 °C (61 °F)	20 °C (68 °F)	
Core #4	20 °C (68 °F)	16 °C (61 °F)	20 °C (68 °F)	
Core #5	20 °C (68 °F)	16 °C (61 °F)	20 °C (68 °F)	

Since the fan seemed to running perfectly I put it all back together to begin fully retesting the computer.

4.3 FIXING THE SOFTWARE FAULT

Since the hardware problems had been fixed I decided to check if the CPU was still running slow by performing another test in “Performance Test” by PassMark.



These results show no major difference in performance from the previous tests 4381 and this tests 4370. I then decide to update the Graphics driver because this includes the AMD Catalyst Control Centre, which can control the CPU as well as the GPU.

The screenshot shows the AMD Support & Drivers page. The main navigation menu includes Products & Technologies, Partners, Developers, and Worldwide. Below the menu, there is a large heading "Graphics Drivers & Software". On the left, there is a sidebar with links for "Play Android™ Games & Apps on your PC" (with a thumbnail of the AMD AppPlayer interface) and "Download AMD AppPlayer" (with a "Learn More" link). Another sidebar highlights "ASUS ROG ARES II: The world's fastest graphics card*" with a thumbnail of the graphics card.

The main content area displays a five-step selection process:

- Step 1:** Select the type of system that you have:
- Step 2:** Select the product family your product belongs to:
- Step 3:** Select your product:
- Step 4:** Select the supported operating system that you have:
- Step 5:** [Display Results](#)

Selecting the Correct Driver


Name	File Size	Revision Number	Release Date	Download Link
Catalyst Software Suite	135 MB	13.4	5/29/2013	Download

Description:
Package contains the following graphics drivers and dependent/required software for the products specified in the current version's official release notes for the 64 bit version of Windows 7 and Windows 8:


- Display Driver ver. 12.104
- OpenCL(tm) Driver ver. 10.0.1124.2
- Catalyst Control Center ver. 2013.0328.2217.38225

Languages:
Czech, Danish, German, Greek, US English, Spanish, Finnish, French, Hungarian, Italian, Japanese, Korean, Dutch, Norwegian, Polish, Portuguese, Russian, Swedish, Thai, Turkish, Chinese (Traditional), Chinese (Simplified)


Selecting the Correct Driver



Extracting Installer




I select all the components that need updating




After a few minute wait it's installed.

After the driver had been updated I opened up the AMD Catalyst Control Centre and navigated to the CPU Power section.



CPU Power Screen

The CPU had been under-clocked previously to 1/3 of its capability, probably to try to combat the overheating problem. So I increased the slider to the max and restarted the computer.



4.4 FULLY RETESTING THE SYSTEM

I first reran the temperature test, because the case was open when the quick test was carried out. However the results were almost the same 30-40°C cooler than on the faulty cooler.

	Temperatures			
	TMPIN0	21 °C (69 °F)	20 °C (68 °F)	23 °C (73 °F)
	TMPIN2	33 °C (91 °F)	31 °C (87 °F)	34 °C (93 °F)
	Fans			
	FANIN0	2407 RPM	1289 RPM	2439 RPM
	Fans PWM			
	CPU	100 %	100 %	100 %
	System Fan 1	100 %	100 %	100 %
	System Fan 2	100 %	100 %	100 %
	System Fan 3	100 %	100 %	100 %
	AMD Phenom II X6 1090T			
	Temperatures			
	Core #0	17 °C (61 °F)	16 °C (60 °F)	20 °C (68 °F)
	Core #1	17 °C (61 °F)	16 °C (61 °F)	20 °C (68 °F)
	Core #2	17 °C (61 °F)	16 °C (60 °F)	20 °C (68 °F)
	Core #3	17 °C (61 °F)	16 °C (60 °F)	20 °C (68 °F)
	Core #4	17 °C (61 °F)	16 °C (61 °F)	20 °C (68 °F)
	Core #5	17 °C (62 °F)	16 °C (60 °F)	20 °C (68 °F)
	Powers			

Idle Temperatures after upgrade


I then reran the Just Cause 2 bench mark and the temperature reached a max of 36°C.

	AMD Phenom II X6 1090T			
	Temperatures			
	Core #0	34 °C (92 °F)	27 °C (81 °F)	36 °C (95 °F)
	Core #1	34 °C (92 °F)	28 °C (81 °F)	36 °C (95 °F)
	Core #2	34 °C (92 °F)	27 °C (81 °F)	36 °C (95 °F)
	Core #3	34 °C (92 °F)	27 °C (81 °F)	36 °C (95 °F)
	Core #4	34 °C (92 °F)	27 °C (81 °F)	36 °C (95 °F)
	Core #5	34 °C (92 °F)	28 °C (81 °F)	36 °C (95 °F)
	Powers			
	Package	136.80 W	58.80 W	136.80 W
	WDC WD1001FALS-00J7B1			
	Temperatures			
	Assembly	42 °C (107 °F)	42 °C (107 °F)	42 °C (107 °F)
	Radeon HD 5770			
	Voltages			
	VINO	0.950 V	0.950 V	1.125 V
	Temperatures			
	TMPIN0	57 °C (134 °F)	46 °C (114 °F)	60 °C (140 °F)

CPU Temps under load after upgrade

Which is a significant improvement from the before upgrade test which reached a max of around 88°C.

I then reran the Performance Test by PassMark again to check if the CPU is running at its full potential after I reversed the under-clock.



While the CPU is still not equal with the other processor of the same model, it's only a 5.4% decrease in performance. This could be attributed to age, overheat damage or the other computer being a fresh install, while this computers has several background processes still using CPU while the test is in progress.

5 REFERENCES

- [1] CPU Max Temp [http://www.cpu-world.com/CPUs/K10/AMD-Phenom%20II%20X6%201090T%20Black%20Edition%20-%20HDT90ZFBK6DGR%20\(HDT90ZFBGRBOX\).html](http://www.cpu-world.com/CPUs/K10/AMD-Phenom%20II%20X6%201090T%20Black%20Edition%20-%20HDT90ZFBK6DGR%20(HDT90ZFBGRBOX).html)
- [2] Zalman CNPS9500A <http://www.newegg.com/Product/Product.aspx?Item=N82E16835118223>
- [3] Zalman CNPS9500A <http://www.amazon.co.uk/dp/B001FW3GS0>
- [4] Arctic Silver 5 (AS5) Paste and Articlean Cleaner <http://www.amazon.co.uk/dp/B003VRBPAI>
- [5] LINDY Anti-Static Service Kit <http://www.amazon.co.uk/dp/B000I2JX3A>
- [6] 5 Star Air Duster Can <http://www.amazon.co.uk/dp/B000MQ7DZC>

Richard Hancock - Unit 25 & 13

[7] Novatech Air Duster Compressed Gas Can (400ml)

<http://www.novatech.co.uk/products/components/pctoolsandkits/mt2607.html>

[8] CNPS9500A LED Manual and Product Page

http://www.zalman.com/global/product/Product_Read.php?Idx=277